


## 1. Back to Charging Dock

Click the "Go to charging" icon, robot will go back to the charging pile automatically.

Note: locating should be correct before clicking the icon.



## 2. Docking

After auto-docking succeeded, the screen will show current charging status.

On-charging: the light indicator of charging pile and light strip of robot turn green. (Fig. 2)

Fully charged: light strip of robot turns blue (Fig. 3)



Fig. 1: Not charged



Fig. 2: Charging



Fig. 3: Fully Charged