



Please read these instructions carefully before using this safety clothing. You should also consult your safety officer or immediate superior with regard to suitable garments for your specific work situation. Store these instructions carefully so that you can consult them at any time.



Refer to the garment label for detailed information on the corresponding standards. All these garments comply with the requirement of Directive 89/686/EEC



EN ISO
20471:2013

EN ISO 20471:2013 High Visibility Warning Clothing signalling the users presence during day and night (see label)

X Class for the fluorescent and reflective surface - 3 Levels

Class 1: Minimum level

Class 2: Intermediate level

Class 3: Highest level

X



EN 343

EN 343 : 2003 + A1:2007

Protection Against Rain (see label)

X Resistance to water penetration - 3 levels

Y Resistance to water vapour penetration - 3 levels

Class 1 Minimum level

Class 2 Intermediate level

Class 3 Highest level

Class 1 Minimum level

Class 2 Intermediate level

Class 3 Highest level

X

Y

Garments with removable sleeves only offer full protection when the sleeves are attached to the body of the garment.

Content Label : Refer to garment label for corresponding content details.

Available Size & Selection : Fit according to correct chest and waist size, refer to size chart. These garments have a built in allowance for comfort and to allow the garment to be worn over medium bulky clothing.

Warning: Where there is a hood, peripheral vision and hearing may be impaired.

Storage : DO NOT store in places subject to direct or strong sunlight. Store in clean, dry conditions.

After care : The manufacturer will not accept liability for garments where care labels have been ignored, defaced or removed.

Recommended maximum continuous wearing time

For a complete suit consisting of jacket and trousers without a thermal lining.

EN 343 : 2003				
		Duration of Wearing (in minutes)		
Temp: Temperature of working environment	Temp	Class 1	Class 2	Class 3
	25°C	60	100	200
	20°C	75	250	—
	15°C	100	—	—
	10°C	240	—	—
	5°C	—	—	—
" — " means: no limit for wearing time				

Water Vapour Permeability effect for coated fabrics or laminates in different ambient temperatures

Wash Care Labels : Refer to garment label for corresponding washing details.



Max wash temp 30°C, very mild process



Max wash temp 60°C, normal process



Do not tumble dry



Iron max 150°C



Max wash temp 40°C, normal process



Do not bleach



Line dry



Do not iron



Max wash temp 40°C, mild process



Tumble dry low



Drip line dry



Do not dry clean



Max wash temp 50°C, mild process