

**Aesculap AG**Postfach 40  
78501 Tuttlingen  
GermanyB.Braun LITHUANIA  
To whom it may concernContact: Jennifer Pirker  
Internet: <http://www.bbraun.com>

Date: October 04, 2016

**Confirmation of Terms & Conditions: Aesculap Technical Service Germany**

Dear Sir or Madam,

we confirm the following conditions valid for the Aesculap Technical Service (ATS) in Germany:

1. Aesculap Technical Service repairs or exchanges all Aesculap products and standard surgical instruments from other manufacturers, as long as we have an equivalent in our portfolio. Our repair portfolio also includes instruments with Noir coating (e.g. scissors / bone punches with titanium aluminium nitride coating).
2. After repair of a surgical instrument, we apply a new product marking and the service code by using validated laser marking technology. The service code consists minimum of ATS + year of repair, but can also contain the month of repair, additionally (depending on the instrument type).
3. For our customers, we provide special transportation boxes on request, which can be used as safe packaging for the shipment of repair goods to ATS and back to the customer.
4. The average internal turnaround time for instrument repairs and exchange in ATS is 7 working days. The turnaround time may differ depending on incoming order volumes.
5. If an instrument is not repairable, we offer our customers to replace it directly with a new Aesculap article, if the product is available in our portfolio. If our customers don't agree to the replacement, the defective instrument will be marked with a special label, explaining the impossibility of repair and sent back unrepaired.

**Chairman of Supervisory Board:**  
Prof. Dr. h.c. Ludwig Georg Braun**Executive Board:**  
Prof. Dr. Hanns-Peter Knaebel  
(Chairman)  
Dr. Jens von Lackum  
Dr. Joachim Schulz**Corporate Office: Tuttlingen**  
Register Court: Stuttgart HRB 726261  
VAT reg. no. DE812160059

WEEE-Reg.-No. DE 65109852

**Bank Account:**  
**Deutsche Bank AG Tuttlingen**  
BLZ 653 700 75 Konto 21 22 000 00  
IBAN DE44 6537 0075 0212 2000 00  
SWIFT / BIC DEUTDE33  
**Baden-Württembergische Bank**  
BLZ 600 501 01 Konto 487 1905  
IBAN DE31 6005 0101 0004 8719 05  
SWIFT / BIC SOLADEST**Address:**  
Aesculap AG  
Am Aesculap-Platz  
78532 Tuttlingen  
Germany

Page 2 to the letter of October 04, 2016 to  
To whom it may concern

6. For ATS contract customers, we have ATS website with the possibility to track the status of an order online, for example if the goods have already arrived in ATS or if they are already booked into the system.

Aesculap AG, 04 October 2016





P. d. 40  
78501 Tuttingenas  
Vokietija

B.Braun Lietuva  
Surinteresuotiems asmenims

Kontaktai: Jennifer Pirker  
Internet.: <http://www.bbraun.com>  
Data: 2016 m. spalio 4 d.

### Patvirtinimas dėl terminų ir sąlygų: AESCULAP Techninis Servisas Vokietijoje

Gerb. ponai,

Šiuo raštu patvirtiname žemiau išvardintas sąlygas, kurios galioja Aesculap Techniniame servise (ATS) Vokietijoje:

1. Aesculap Techninis Servisas taiso (renovuoja) arba keičia naujais visus Aesculap instrumentus ir standartinius chirurginius instrumentus iš kitų gamintojų, jei prekių pasiūloje turi lygiaverčių parametrų instrumentus. Mūsų renovacija apima instrumentus su Noir padengimu (pvz.: žirklys/kaulinės žnyplės su titano aliuminio nitrido padengimu).
2. Po chirurginio instrumento renovacijos, mes uždedame naują prekės žymėjimą ir atlikto serviso kodą naudojant patvirtintą lazerinio žymėjimo technologiją. Atlikto serviso kodą minimaliai sudaro ATS ženklas + renovacijos metai ir mėnesis papildomai (priklausomai nuo instrumento tipo).
3. Mūsų klientams suteikiame specialiai pritaikytas transportavimo dėžes, kurios gali būti naudojamos renovuotų instrumentų saugiam pakavimui ir transportavimui į ATS ir atgal klientui.
4. Vidutinis vidinis instrumentų renovacijos ir pakeitimo laikas ATS užtrunka 7 darbo dienas. Laikas gali keistis priklausomai nuo gautų užsakymų kiekio.
5. Jei instrumentas yra nesutaisomas, klientams siūlome pakeisti jį nauju Aesculap instrumentu jei tokį turime prekių pasiūloje. Jei klientas nesutinka pakeisti, nepataisomas instrumentas pažymimas specialia etikete, kuri paaiškina instrumento renovacijos negalimumą, ir išsiunčiamas atgal.
6. Klientams, turintiems sutartį su ATS, galime pasiūlyti internetinį puslapį, kuriame galima pasitikrinti kokioje stadijoje yra užsakymas, pavyzdžiui, ar instrumentai jau atvyko į ATS arba ar jie jau sistemiškai tikrinami.

Aesculap AG, 2016 spalio 04  
i.V.

Stebėtojų tarybos pirmininkas:  
Prof. dr.h. c. Ludwig Georg  
Braun

Administracijos valdyba:  
Prof. dr. Hanns-Peter Knaebel  
(pirmininkas)  
Dr. Harald Stallforth  
(pirmininko pavaduotojas)  
Dr. Joachim Schulz

Įmonės buveinė: Tuttingenas  
Teismo registras:  
Štutgartas HRB 726261  
PVM kodas: DE812160059  
WEEE Reg.Nr. DE 65109852

Banko sąskaita:  
„Deutsche Bank AG“ Tuttingenas  
BLZ 653 700 75, sąsk. 21 22 000  
IBAN DE44 6537 0075 0212 2000 00  
SWIFT kodas: DEUT DESS 603

Adresas:  
„Aesculap AG“  
Am Aesculap-Platz  
78532 Tuttingenas  
Vokietija