

Świadectwo z badań 128/18

egzemplarz nr.

Zleceniodawca: „MIRANDA” Spółka z o.o.
Adres: 62-700 Turek, ul. Jedwabnicza 1
Przedmiot badań: Tkanina obiciowa
 Tkanina poliestrowa EVO 3, kol. Żółty, ozn: nr partii P/GT/18/01/0144
Symbol: EVO-
Specyfikacja Techniczna przedmiotu badań: -
Zakres badań: wg umowy zlecenia 128,129,130/18
Data przyjęcia próbki do magazynu: 28.06.2018 r.
Data sporządzenia świadectwa z badań: 13.07.2018 r.
Sposób pobrania i dostarczenia próbki: Próbka pobrana i dostarczona przez zleceniodawcę
Numer próbki: 128/18

Wykonano w trzech jednobrzmiących egzemplarzach, po jednym dla:


1. „MIRANDA” spółka z o.o., 62-700 Turek, ul. Jedwabnicza 1
2. LBWWiS
3. Kancelaria WOBWSM


Wyniki badań

Lp.	Wskaźnik	Jedn.	Metoda badania	Wynik	Uwagi
1.	odporność na ścieranie	[suwy]	PN-EN ISO 12947-2:2017-02	180 000	wyznaczanie zniszczenia próbki przy nacisku 12 kPa, całkowita masa obciążenia (795±7)g, badanie zatrzymane dla wartości 180 000-brak zniszczenia próbki

Uwagi:

- 1) Wyniki badań przedstawione w tabeli odnoszą się wyłącznie do badanej próbki.
- 2) Wskaźnik nie objęty zakresem akredytacji, jeśli występuje, oznaczono symbolem *) umieszczonym w tabeli wyników przy nazwie wskaźnika.
- 3) Za symbolem ± przy wyniku badania podano wartość niepewności rozszerzonej przy współczynniku rozszerzenia k=2 i przyjętym poziomie ufności 95%

Wykonał:

Autoryzował:
 wz. Kierownik LBWWiS


UWAGA !Bez pisemnej zgody LBWWiS, niniejszy dokument nie może być powielany inaczej, jak tylko w całości LBWWiS nie pobiera próbek do badań laboratoryjnych.

Test Certificate 128/18

copy no.:

Ordering Entity:

“MIRANDA” Spółka z o.o.

Address:

62-700 Turek, ul. Jedwabnicza 1

Test subject:

Upholstery material

EVO 3 upholstery material, colour Yellow, marking: batch no.
P/GT/18/01/0144

Symbol:

EVO-

Technical specification of the test subject

Scope of tests:

**Date of sample receipt to
the warehouse:**

acc. to order contract 128,129,130/18

Date of the test certificate:

28 June 2018

**Method of sample
collection
and delivery**

13 July 2018

Sample collected and delivered by the ordering entity

Sample number:

128/18

Prepared in three identical copies, one for:

1. “MIRANDA” spółka z o.o., 62-700 Turek, ul. Jedwabnicza 1
2. LBWWS
3. WOBWSM Office

Test results

No.	Index	Unit	Test method	Result	Comments
1.	abrasion resistance	[strokes]	PN-EN ISO 12947-2:2017-02	180,000	determination of sample destruction at the pressure of 12 kPa, total ballast weight (795±7)g, test stopped for the value of 180 000-no sample destruction

Comments:

- 1) Test results presented in the table refer only to the tested sample.
- 2) Test results not covered by the scope of the accreditation, if any, are marked with *) in the result table at the index name.
- 3) Behind the symbol and next to the test result the value of extended uncertainty is provided with the coverage factor $k = 2$ and adopted confidence level of 95%.

Performed by:

Authorised by:

p.p. Manager of LBWWS

Senior Specialist
Laboratorium Badań WYROBÓW
Włókienniczych i Skórzanych
Dorota Marciniak, M.Sc.

NOTE: Without the written consent of LBWWS this document may be reproduced only in its entirety. LBWWS does not collect samples for laboratory tests.